
ZX Spectrum Issue 1 and early Issue 2: Spider / Dead Cockroach timing fix for ULA 5C102

Note: the 47LS00 is shown as

mounted: upside down!



especially because setting the I register to this range causes problems on other

machines. (Note: the I register is put on A8-A15 in the refresh cycle.)

Last updated: 2005-12-12

kio@little-bat.de

/RFSH

